



REPORTING IMPROPER OPERATIONS OR MAINTENANCE
OF
STORMWATER MANAGEMENT PRACTICES

Should there be evidence of improper operations or improper maintenance of stormwater management practices, the Borough of Parkesburg should be notified. For non-emergency situations, written notification should be provided of the specifics.

Stormwater management practices include structural BMPs (best management practices). Common structural BMPs in the Borough include, but are not limited to, subsurface infiltration beds and detention basins.

Detection of illicit discharges from an outfall into Little Buck Run may be an indication of poor operation and maintenance of structural BMPs or possibly another means of pollution. In any event, detection of illicit discharges should be reported immediately to the Borough.